

# ANALIZA STANJA VOZILA - VEHICLE CONDITION ANALYSIS

Na zahtev stranke:

**IVECO Austria Gesellschaft m.b.H.**

**IVECO Stralis**



VIN:	WJMM62AUZ0C437636
Vrsta vozila/Vehicle type:	teretno
Godina proizvodnje/Production year:	2020
Datum prve registracije/First registration date:	28.10.2024
Registarska oznaka/License plate:	ČA125-NO
Vrsta menjača/Type of gearbox:	automatski / automatic
Boja vozila/Vehicle color:	s bela m
Broj osovina/Number of axles:	2
Broj točkova/Number of wheels:	6
Radna zapremina u cm <sup>3</sup> /Engine displacement in cm <sup>3</sup> :	11120
Snaga u kW/Engine power in kW:	353
Pogonsko gorivo/The type of fuel:	dizel
Pređena kilometraža/Mileage:	355733
Saobraćajna dozvola/Vehicle registration:	da / yes
Motor pokrenut/Engine running:	da / yes
Probna vožnja/Test drive:	ne / no

## IVECO Stralis

### 1.2. OPREMA VOZILA/VEHICLE ACCESSORIES

- |   |   |
|---|---|
| *servo upravljač / power steering                 | *vazdušni jastuk / AIR Beg                            |
| *klima uređaj / air condition                     | *radio uređaj / radio                                 |
| *centralno zaključavanje / central lock           | *putni računar / trip computer                        |
| *svetla za maglu / fog lights                     | *dnevna svetla / daylight                             |
| *EL. podesivi retrovizori / El. mirror adjustment | *sedišta podesiva po visini / height adjustable seats |
| *EL. podizači stakala / Electric windows          | *USB slot   |
| *multif upravljač / multif steering wheel         | *spavaća kabina / sleeping cabin                      |
| *retarder / retarder                              | *parking klima / parking air conditioning             |

### 1.3. PNEUMATICI/TIRES

	TIP FELNE RIM TYPE	MARKA BRAND	DIMENZIJA DIMENSION	mm mm	SEZONA SEASON
PREDNJI LEVI FRONT LEFT	čelik/steel	MICHELIN	315/70 R 22,5	7,2	Z/W
PREDNJI DESNI FRONT RIGHT	čelik/steel	MICHELIN	315/70 R 22,5	8,2	Z/W
ZADNJI DESNI SPOLJNI REAR RIGHT OUTER	čelik/steel	MICHELIN	315/70 R 22,5	7,2	Z/W
ZADNJI DESNI UNUTRAŠNJI REAR RIGHT INNER	čelik/steel	MICHELIN	315/70 R 22,5	8,6	Z/W
ZADNJI LEVI SPOLJNI REAR LEFT OUTER	čelik/steel	MICHELIN	315/70 R 22,5	9,6	Z/W
ZADNJI LEVI UNUTRAŠNJI REAR LEFT INNER	čelik/steel	MICHELIN	315/70 R 22,5	9,8	Z/W

## IVECO Stralis

### 2.0. ZATEČENO STANJE - VEHICLE CONDITION

#### 2.1. ZAPAŽANJE - SPOLJAŠNJOST / OBSERVATION - EXTERIOR

Vozilo je u generalno dobrom stanju. Na vozilu postoje određena oštećenja i tragovi korišćenja srazmerni starosti i nameni vozila. Vetrobransko staklo ima oštećenje. Svetlosne grupe su u dobrom stanju. Za vreme pregleda su primećeni određeni tragovi masnoće ispod vozila. Pneumatici su u dobrom stanju.

The vehicle is in generally good condition. The vehicle has some damage and signs of use commensurate with the age and purpose of the vehicle. The windshield is damaged. The light groups are in good condition. During the inspection, certain traces of grease were noticed under the vehicle. The tires are in good condition.

#### 2.2. ZAPAŽANJE - UNUTRAŠNJOST VOZILA / OBSERVATION - INTERIOR

Enterijer vozila je kompletan, zaprljan, sa određenim tragovima korišćenja i oštećenja. The interior of the vehicle is complete, dirty, with certain traces of use and damage.

#### Uočena oštećenja na vozilu - Observed damage to the vehicle:

* podvozje vozila/under the vehicle chassis	* tragovi zamašćenosti/traces of oiliness
* desna unutrašnja ostava/right inner storage	* zaprljano / dirty
* zavese/curtains	* zaprljano / dirty
* rukonaslon vozačevog sedišta/driver's seat armrest	* oštećeno / damaged
* leva I desna donja ostava pored ležaja/left and right lower storage room next to the bed	* oštećeno / damaged
* donji dušek/bottom mattress	* zaprljano / dirty
* tapacirung ispod gornjeg ležaja/upholstery under the upper bed	* zaprljano / dirty
* tapacirung iza ležaja/upholstery behind the bed	* zaprljano / dirty
* svetlo u vozačevim vratima/light in the driver's door	* ne fiksirano/not fixed
* obe gume levo na zadnjoj osovini/both tires left on rear axle	* potrošene / to much worn
* mat folija vozačevih I suvozačevih vrata/matte foil for the driver's and passenger's doors	* oštećeno / damaged
* keder na vozačevoj strani/cedar on the driver's side	* oštećeno / damaged
* ogrebotine iznad fara/scratches above the headlights	* ogrebotine / scratches
* gornji prtljažnik na levoj strani/upper luggage compartment on the left side	* oštećeno / damaged
* suvozačeva vrata/passenger door	* oštećeno / damaged

## IVECO Stralis

\* desna lajsna vetrobranskog stakla/right windshield molding \* oštećeno / damaged

\* plastika levog retrovizora/left rearview mirror plastic \* oštećeno / damaged

\* termoizolacija kabine/  
thermal insulation of the cabin \* oštećeno / damaged


## IVECO Stralis

### 3.0. FOTO ELABORAT I ZAPAŽANJE / PHOTO ELABORATION AND OBSERVATIONS




## IVECO Stralis

### 3.0. FOTO ELABORAT I ZAPAŽANJE / PHOTO ELABORATION AND OBSERVATIONS




## IVECO Stralis

### 3.0. FOTO ELABORAT I ZAPAŽANJE / PHOTO ELABORATION AND OBSERVATIONS




## IVECO Stralis

### 3.0. FOTO ELABORAT I ZAPAŽANJE / PHOTO ELABORATION AND OBSERVATIONS



## IVECO Stralis

### 3.0. FOTO ELABORAT I ZAPAŽANJE / PHOTO ELABORATION AND OBSERVATIONS



## IVECO Stralis

### 4.0. DODATNA ZAPAŽANJA / ADDITIONAL OBSERVATIONS



## IVECO Stralis

### 4.0. DODATNA ZAPAŽANJA / ADDITIONAL OBSERVATIONS



**Mesto i datum pregleda / Place and date:**

**Datum izrade analize / Date of analysis:**

**Pregledu prisustvovali / The examination was attended by:**

**Čačak, 15.3.2024**

**18.3.2024**

**Milan Vasiljević, Nikola Stamenković**

**Vozilo pregledao / Assessor:**

**Nikola Pajević**



**Odobrio / Approved:**

**Šef Službe**

**Procena štete i ekspertize**

**Head of Department**

**Claims & Expertise**

**Nikola Stamenković**

## 5.0 TROŠKOVI POPRAVKE VOZILA / VEHICLE REPAIR COSTS

### 5.1 Troškovi delovi / Parts costs

NAZIV/NAME	ID.NR	KOLIČINA/QUANTITY	CENA/ PRICE	UKUPNO/TOTAL
podvozje vozila zamašćeno/traces of grease under the vehicle chassis	garancija/warranty	-	- €	- €
desna unutrašnja ostava/right inner storage	čišćenje/cleaning	1,00	30,00 €	30,00 €
zavese/curtains	pranje, postavljanje/cleaning, instalation	1,00	70,00 €	70,00 €
rukonaslon vozačevog sedišta/driver's seat armrest	42580838	1,00	223,68 €	223,68 €
leva i desna donja ostava pored ležaja/left and right lower storage room next to the bed	5802704282+5802450919	1,00	28,05 €	28,05 €
donji dušek/bottom mattress	pranje, postavljanje/cleaning, instalation	1,00	40,00 €	40,00 €
tapacirung ispod gornjeg ležaja/upholstery under the upper bed	dubinsko pranje/deep	1,00	30,00 €	30,00 €
tapacirung iza ležaja/upholstery behind the bed	dubinsko pranje/deep	1,00	30,00 €	30,00 €
svetlo u vozačevim vratima/light in the driver's door	5802300990	1,00	9,73 €	9,73 €
termoizolacija kabine/thermal insulation of the cabin	5802344095	1,00	877,30 €	877,30 €
mat folija vozačevih i suvozačevih vrata/matte foil for the driver's and passenger's doors	5802439504+5802439508	1,00	10,88 €	10,88 €
keder na vozačevoj strani/cedar on the driver's side	5802576549	1,00	52,05 €	52,05 €
ogrebotine iznad fara/scratches above the headlights	čišćenje i poliranje/cleaning and polishing	1,00	40,00 €	40,00 €
gornji prtljažnik na levoj strani/upper luggage compartment on the left side	farbanje/cleaning and paint job	1,00	50,00 €	50,00 €
suvozačeva vrata/passenger door	farbanje/preparation and paint job	1,00	50,00 €	50,00 €
desna lajsna vetrobranskog stakla/right windshield molding	5802357391	1,00	22,27 €	22,27 €
plastika levog retrovizora/left rearview mirror plastic	popravka/repair	1,00	30,00 €	30,00 €
				- €
		-	- €	- €
		-	- €	- €
		-	- €	- €
		-	- €	- €

